Devices List

Created by using DevManView

Device Name	Manufacturer	Service	Device Type Code	Device Type Name	Device Instance ID	Location	Capabilities	Config Flags	Disabled	Connected	Device Registry Time 1	Device Registry Time 2	Drive Letter	Container ID	Driver Description	Driver Version	.inf File	.inf Section	Driver Date	Driver Registry Time
@oem24.inf,%Phone.AppleUSB.DeviceDesc%;Apple Mobile Device USB Composite Device	Apple, Inc.	usbccgp	USBDevice		USB\VID_05AC&PID_12A8\c7d4dddd99f60e2fc042bd996b5a7df28044331fb	Port_#0003.Hub_#0008	0x00000094	0x00000000	No	No	02/06/2019 18:03:32	02/06/2019 18:03:32		{77b1ab0e-6a34-5274-a0f8-52b576fd0dacd}	Apple Mobile Device USB Composite Device	423.36.0.0	oem24.inf	AppleUSB_CCGPDriver\Install.NT	07/05/2018	02/06/2019 18:03:32
@oem24.inf,%Phone.AppleUsbMux.DeviceDesc%;Apple Mobile Device USB Device	Apple, Inc.	WinUSB	USBDevice		USB\VID_05AC&PID_12A8&MI_01\7&2fd9e732&0&0001	0005.0000.0000.003.000.000.000.000.000	0x00000084	0x00000000	No	No	02/06/2019 18:03:33	02/06/2019 18:03:33		{77b1ab0e-6a34-5274-a0f8-52b576fd0dacd}	Apple Mobile Device USB Device	423.36.0.0	oem24.inf	AppleUsbMux_Install	07/05/2018	02/06/2019 18:03:33
@System32\drivers\usbehci.sys,#1073807361;Controller host %1 USB %2 extensible - %3 (Microsoft);(Etron,3.0.1.0)	Generic USB xHCI Host Controller	USBXHCI	USB		PCI\VEN_1912&DEV_7052&SUBSYS_75521849&REV_00\4&1f2757ba&0&00AA	@System32\drivers\pci.sys,#65536;PCI bus %1, device %2, function %3;(5,0,0)	0x00000000	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 01:06:20		{00000000-0000-0000-FFFF-ffffffffffff}	USB xHCI Compliant Host Controller	10.0.17763.1	usbxhci.inf	Generic.Install.NT	14/09/2018	11/05/2019 00:58:54
ACPI Fixed Feature Button	(Standard system devices)		System		ACPI\FixedButton\2&daba3ff&2		0x00000080	0x00000000	No	No	11/05/2019 01:03:37			{00000000-0000-0000-FFFF-ffffffffffff}	ACPI Fixed Feature Button	10.0.17763.1	machine.inf	NO_DRV	21/06/2006	11/05/2019 00:58:54
ACPI Power Button	(Standard system devices)		System		ACPI\PNP0C0C\aa		0x00000070	0x00000000	No	No	11/05/2019 01:03:37			{00000000-0000-0000-FFFF-ffffffffffff}	ACPI Power Button	10.0.17763.1	machine.inf	NO_DRV	21/06/2006	11/05/2019 00:58:54
ACPI x64-based PC	(Standard computers)	\Driver\ACPI_HAL	Computer		ROOT\ACPI_HAL\0000		0x00000000	0x00000000	No	No	03/06/2019 20:55:30			{00000000-0000-0000-FFFF-ffffffffffff}	ACPI x64-based PC	10.0.17763.1	hal.inf	ACPI_AMD64_HAL	21/06/2006	11/05/2019 00:58:53
Adobe PDF	Adobe		PrintQueue		SWD\PRINTENUM\{FB4CFFA1-A71B-4EE0-92C8-5ABBA38C9B19}		0x00000084	0x00000000	No	No	11/05/2019 01:21:32			{15902c7d-d806-1249-7391-deb4198c5e9a}	Local Print Queue	10.0.17763.1	printqueue.inf	NO_DRV_LOCAL	21/06/2006	11/05/2019 01:21:32
Altoparlanti (Realtek High Definition Audio)	Microsoft		AudioEndpoint		SWD\MMDEVAPI\{0.0.0.00000000}.{5bcd357-fcb8-4142-9740-067deb19edce}		0x00000084	0x00000000	No	No	11/05/2019 11:32:00			{1e60dca8-7ac1-59c0-b39d-42853a8d8c039}	Audio Endpoint	10.0.17763.1	audioendpoint.inf	NO_DRV	14/09/2018	11/05/2019 11:32:00
Altoparlanti (WsAudioDevice_3835(1))	Microsoft		AudioEndpoint		SWD\MMDEVAPI\{0.0.0.00000000}.{ab999d46-1c26-42fe-8cca-4d5ab335f9d7}		0x00000080	0x00000000	No	No	11/05/2019 01:06:21			{00000000-0000-0000-FFFF-ffffffffffff}	Audio Endpoint	10.0.17763.1	audioendpoint.inf	NO_DRV	14/09/2018	11/05/2019 01:06:21
AMD FX-8320E Eight-Core Processor	Advanced Micro Devices	AmdPPM	Processor		ACPI\AuthenticAMD_-_AMD64_Family_21_Model_2_-_AMD_FX-8320E_Eight-Core_Processor______1		0x00000030	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 00:58:54		{00000000-0000-0000-FFFF-ffffffffffff}	AMD Processor	10.0.17763.503	cpu.inf	AmdPPM_Inst.NT	21/04/2009	19/05/2019 16:33:12
AMD FX-8320E Eight-Core Processor	Advanced Micro Devices	AmdPPM	Processor		ACPI\AuthenticAMD_-_AMD64_Family_21_Model_2_-_AMD_FX-8320E_Eight-Core_Processor______2		0x00000030	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 00:58:54		{00000000-0000-0000-FFFF-ffffffffffff}	AMD Processor	10.0.17763.503	cpu.inf	AmdPPM_Inst.NT	21/04/2009	19/05/2019 16:33:12
AMD FX-8320E Eight-Core Processor	Advanced Micro Devices	AmdPPM	Processor		ACPI\AuthenticAMD_-_AMD64_Family_21_Model_2_-_AMD_FX-8320E_Eight-Core_Processor______3		0x00000030	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 00:58:54		{00000000-0000-0000-FFFF-ffffffffffff}	AMD Processor	10.0.17763.503	cpu.inf	AmdPPM_Inst.NT	21/04/2009	19/05/2019 16:33:12
AMD FX-8320E Eight-Core Processor	Advanced Micro Devices	AmdPPM	Processor		ACPI\AuthenticAMD_-_AMD64_Family_21_Model_2_-_AMD_FX-8320E_Eight-Core_Processor______4		0x00000030	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 00:58:54		{00000000-0000-0000-FFFF-ffffffffffff}	AMD Processor	10.0.17763.503	cpu.inf	AmdPPM_Inst.NT	21/04/2009	19/05/2019 16:33:12
AMD FX-8320E Eight-Core Processor	Advanced Micro Devices	AmdPPM	Processor		ACPI\AuthenticAMD_-_AMD64_Family_21_Model_2_-_AMD_FX-8320E_Eight-Core_Processor______5		0x00000030	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 00:58:54		{00000000-0000-0000-FFFF-ffffffffffff}	AMD Processor	10.0.17763.503	cpu.inf	AmdPPM_Inst.NT	21/04/2009	19/05/2019 16:33:12
AMD FX-8320E Eight-Core Processor	Advanced Micro Devices	AmdPPM	Processor		ACPI\AuthenticAMD_-_AMD64_Family_21_Model_2_-_AMD_FX-8320E_Eight-Core_Processor______6		0x00000030	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 00:58:54		{00000000-0000-0000-FFFF-ffffffffffff}	AMD Processor	10.0.17763.503	cpu.inf	AmdPPM_Inst.NT	21/04/2009	19/05/2019 16:33:12
AMD FX-8320E Eight-Core Processor	Advanced Micro Devices	AmdPPM	Processor		ACPI\AuthenticAMD_-_AMD64_Family_21_Model_2_-_AMD_FX-8320E_Eight-Core_Processor______7		0x00000030	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 00:58:54		{00000000-0000-0000-FFFF-ffffffffffff}	AMD Processor	10.0.17763.503	cpu.inf	AmdPPM_Inst.NT	21/04/2009	19/05/2019 16:33:12
AMD FX-8320E Eight-Core Processor	Advanced Micro Devices	AmdPPM	Processor		ACPI\AuthenticAMD_-_AMD64_Family_21_Model_2_-_AMD_FX-8320E_Eight-Core_Processor______8		0x00000030	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 00:58:54		{00000000-0000-0000-FFFF-ffffffffffff}	AMD Processor	10.0.17763.503	cpu.inf	AmdPPM_Inst.NT	21/04/2009	19/05/2019 16:33:12
AMD High Definition Audio Device	Advanced Micro Devices	AtiHDAudioService	MEDIA		HDAUDIO\FUNC_01&VEN_1002&DEV_AA01&SUBSYS_00AA0100&REV_1005\5&226bda96&0&0001	Internal High Definition Audio Bus	0x00000084	0x00000000	No	Yes	11/05/2019 01:06:58	11/05/2019 01:07:00		{00000000-0000-0000-FFFF-ffffffffffff}	AMD High Definition Audio Device	10.0.1.7	oem9.inf	HDAudioInstall	30/03/2018	03/06/2019 20:55:47
AMD IO Driver	AMD, Inc.	amdiocx64	System		ROOT\SYSTEM\0001		0x00000080	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 00:58:54		{00000000-0000-0000-FFFF-ffffffffffff}	AMD IO Driver	1.0.0.15	oem10.inf	amdiocx64_Inst.NTamd64	18/02/2010	11/05/2019 01:06:09
AMD PCI IDE Controller	Advanced Micro Devices	amdide64	HDC		PCI\VEN_1002&DEV_439C&SUBSYS_439C1849&REV_40\3&267a616a&0&A1	@System32\drivers\pci.sys,#65536;PCI bus %1, device %2, function %3;(0,20,1)	0x00000000	0x00000000	No	Yes	03/06/2019 20:55:31	11/05/2019 00:58:54		{00000000-0000-0000-FFFF-ffffffffffff}	AMD PCI IDE Controller	5.2.2.179	oem17.inf	amdide_Inst_64	28/06/2013	11/05/2019 11:38:53
AMD Radeon (TM) R7 360 Series	Advanced Micro Devices, Inc.	amdkmdap	Display		PCI\VEN_1002&DEV_665F&SUBSYS_E322174B&REV_81\4&f1d09f1&0&0010	@System32\drivers\pci.sys,#65536;PCI bus %1, device %2, function %3;(1,0,0)	0x00000000	0x00000000	No	Yes	11/05/2019 11:28:51	02/06/2019 16:33:39		{00000000-0000-0000-FFFF-ffffffffffff}	AMD Radeon (TM) R7 360 Series	25.20.15031.9002	oem30.inf	ati2mtag_R50D05	15/04/2019	03/06/2019 20:56:08
AMD SATA Controller (IDE Mode)	Advanced Micro Devices	amdide64	HDC		PCI\VEN_1002&DEV_4390&SUBSYS_43901849&REV_40\3&267a616a&0&88	@System32\drivers\pci.sys,#65536;PCI bus %1, device %2, function %3;(0,17,0)	0x00000000	0x00000000	No	Yes	03/06/2019 20:55:31	11/05/2019 11:49:16		{00000000-0000-0000-FFFF-ffffffffffff}	AMD SATA Controller (IDE Mode)	5.2.2.179	oem17.inf	amdide_Inst_64	28/06/2013	11/05/2019 11:38:52
AMD SMBus	Advanced Micro Devices, Inc		System		PCI\VEN_1002&DEV_4385&SUBSYS_43851849&REV_42\3&267a616a&0&A0	@System32\drivers\pci.sys,#65536;PCI bus %1, device %2, function %3;(0,20,0)	0x00000080	0x00000000	No	No	11/05/2019 11:49:16	11/05/2019 00:58:54		{00000000-0000-0000-FFFF-ffffffffffff}	AMD SMBus	5.12.0.38	oem19.inf	AMDSMBus64	17/04/2018	11/05/2019 11:40:08
Apple iPhone	Apple Inc.	WUDFWpdMtp	WPD		USB\VID_05AC&PID_12A8&MI_00\7&2fd9e732&0&0000	0005.0000.0000.003.000.000.000.000.000	0x00000080	0x00000000	No	No	02/06/2019 18:03:39	02/06/2019 18:03:39		{77b1ab0e-6a34-5274-a0f8-52b576fd0dacd}	Apple iPhone	10.0.17763.1	wpdmtp.inf	MTP.NT	21/06/2006	02/06/2019 18:03:39
ASMedia USB Root Hub	(Standard USB Host Controller)	asmthub3	USB		USB\ASMEDIA\ROOT_Hub\5&110ccc0a\0&0&0		0x00000080	0x00000000	No	Yes	11/05/2019 01:36:59			{00000000-0000-0000-FFFF-ffffffffffff}	ASMedia USB Root Hub	1.16.35.1	oem29.inf	RootHub_Product8_Install.NTamd64	11/04/2016	11/05/2019 01:36:59
ASMedia USB3.1 eXtensible Host Controller (ASM1143)	ASMedia Technology Inc	asmtxhci	USB		PCI\VEN_1B21&DEV_1343&SUBSYS_13431B21&REV_00\4&11e7f7e8&0&0048	@System32\drivers\pci.sys,#65536;PCI bus %1, device %2, function %3;(2,0,0)	0x00000080	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 01:06:18		{00000000-0000-0000-FFFF-ffffffffffff}	ASMedia USB3.1 eXtensible Host Controller (ASM1143)	1.16.35.1	oem8.inf	ASMEDIA_Product14_Install.NTamd64	11/04/2016	11/05/2019 01:06:18
ASRock 3TB+ Unlocker	ASRock	AsrVDrive	SCSIAdapter		ROOT\SCSIADAPTER\0001		0x00000000	0x00000000	No	Yes	30/05/2019 23:01:32	30/05/2019 23:01:32		{00000000-0000-0000-FFFF-ffffffffffff}	ASRock 3TB+ Unlocker	1.1.0.0	oem22.inf	Miniport	01/10/2012	30/05/2019 23:01:31
ASRock 3TB+ Unlocker SCSI Disk Device	(Standard disk drives)	disk	DiskDrive		SCSI\Disk&Ven_ASRock&Prod_3TB+_Unlocker\1&1843ccbc&0&000000	Bus Number 0, Target Id 0, LUN 0	0x00000060	0x00000000	No	Yes	30/05/2019 23:01:32	30/05/2019 23:01:32		{00000000-0000-0000-FFFF-ffffffffffff}	Disk drive	10.0.17763.1	disk.inf	disk_install.NT	21/06/2006	30/05/2019 23:01:32
ASRock RAM Disk	ASRock	AsrRamDisk	SCSIAdapter		ROOT\SCSIADAPTER\0002		0x00000000	0x00000000	No	Yes	30/05/2019 23:03:37	30/05/2019 23:03:37		{00000000-0000-0000-FFFF-ffffffffffff}	ASRock RAM Disk	1.0.4.0	oem23.inf	Miniport	19/05/2014	30/05/2019 23:03:37
ASUS DRW-24F1MT ATA Device	(Standard CD-ROM drives)	cdrom	CDROM		IDE\CdRomASUS_DRW-24F1MT______1.00____\5&1bea5509&0&0.1.0	Channel 0, Target 1, Lun 0	0x00000060	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 00:58:55	D:\	{00000000-0000-0000-FFFF-ffffffffffff}	CD-ROM Drive	10.0.17763.1	cdrom.inf	cdrom_install	21/06/2006	11/05/2019 00:58:55
ATA Channel 0	(Standard IDE ATA/ATAPI controllers)	atapi	HDC		PCI\IDE\IDEChannel\4&14edaa04&0&0	Channel 0	0x00000000	0x00000000	No	Yes	11/05/2019 01:03:37	03/06/2019 20:56:11		{00000000-0000-0000-FFFF-ffffffffffff}	IDE Channel	10.0.17763.168	mshdc.inf	atapi_Inst	21/06/2006	11/05/2019 00:58:54
ATA Channel 0	(Standard IDE ATA/ATAPI controllers)	atapi	HDC		PCI\IDE\IDEChannel\4&24144a00&0&0	Channel 0	0x00000000	0x00000000	No	Yes	11/05/2019 01:03:37	03/06/2019 20:56:11		{00000000-0000-0000-FFFF-ffffffffffff}	IDE Channel	10.0.17763.168	mshdc.inf	atapi_Inst	21/06/2006	11/05/2019 00:58:54
ATA Channel 1	(Standard IDE ATA/ATAPI controllers)	atapi	HDC		PCI\IDE\IDEChannel\4&14edaa04&0&1	Channel 1	0x00000000	0x00000000	No	Yes	11/05/2019 01:03:37	03/06/2019 20:56:11		{00000000-0000-0000-FFFF-ffffffffffff}	IDE Channel	10.0.17763.168	mshdc.inf	atapi_Inst	21/06/2006	11/05/2019 00:58:54
ATA Channel 1	(Standard IDE ATA/ATAPI controllers)	atapi	HDC		PCI\IDE\IDEChannel\4&24144a00&0&1	Channel 1	0x00000000	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 11:28:56		{00000000-0000-0000-FFFF-ffffffffffff}	IDE Channel	10.0.17763.168	mshdc.inf	atapi_Inst	21/06/2006	11/05/2019 00:58:54
Coda di stampa radice	Microsoft		PrintQueue		SWD\PRINTENUM\PrintQueues		0x00000080	0x00000000	No	No	11/05/2019 01:06:41			{00000000-0000-0000-FFFF-ffffffffffff}	Local Print Queue	10.0.17763.1	printqueue.inf	NO_DRV_LOCAL	21/06/2006	11/05/2019 01:06:41
Composite Bus Enumerator	Microsoft	CompositeBus	System		ROOT\CompositeBus\0000		0x00000000	0x00000000	No	Yes	11/05/2019 00:59:14	11/05/2019 00:58:59		{00000000-0000-0000-FFFF-ffffffffffff}	Composite Bus Enumerator	10.0.17763.1	compositebus.inf	CompositeBus_Device.NT	21/06/2006	11/05/2019 00:58:53
Connessione rete wireless	Microsoft		SoftwareDevice		SWD\IRADIO\{2103681D-E42B-40D8-BE83-28D66FEB81F}		0x00000080	0x00000000	No	No	11/05/2019 01:26:14			{00000000-0000-0000-FFFF-ffffffffffff}	Generic software device	10.0.17763.1	c_swdevice.inf	SoftwareDevice	21/06/2006	11/05/2019 01:26:14
Direct memory access controller	(Standard system devices)		System		ACPI\PNP0200\4&8ab8035&0		0x00000020	0x00000000	No	No	11/05/2019 00:59:14	11/05/2019 00:58:54		{00000000-0000-0000-FFFF-ffffffffffff}	Direct memory access controller	10.0.17763.1	machine.inf	NO_DRV_X	21/06/2006	11/05/2019 00:58:54
ELBY CLONEDRIVE SCSI CdRom Device	(Standard CD-ROM drives)	cdrom	CDROM		SCSI\CdRom&Ven_ELBY&Prod_CLONEDRIVE\1&2a87d61&1&000000	Bus Number 0, Target Id 0, LUN 0	0x00000060	0x00000000	No	Yes	11/05/2019 01:05:57	11/05/2019 01:05:57	F:\	{00000000-0000-0000-FFFF-ffffffffffff}	CD-ROM Drive	10.0.17763.1	cdrom.inf	cdrom_install	21/06/2006	11/05/2019 01:05:57
Elements	WD	WUDFWpdFs	WPD		SWD\WPDBUSENUM\{45a6d187-f3ec-11e8-a06c-806e6f6e6963}#000000000010000		0x00000080	0x00000000	No	No	25/05/2019 12:34:50	27/05/2019 18:47:24		{5834a676-9e57-5aed-a6ae-4777424cdabe}	Driver volume con file system WPD	10.0.17763.1	wpdfs.inf	Basic_Install	21/06/2006	25/05/2019 12:34:45
Fax	Microsoft		PrintQueue		SWD\PRINTENUM\{B13D3F0-92F0-4EDA-ABC7-249F729C91CF}		0x00000084	0x00000000	No	No	11/05/2019 01:21:32			{ca0e9a60-3e97-fcac-730a-8c0806fa2581}	Local Print Queue	10.0.17763.1	printqueue.inf	NO_DRV_LOCAL	21/06/2006	11/05/2019 01:21:32
G:\	WD	WUDFWpdFs	WPD		SWD\WPDENUM\{84baaa4a-4862-11e6-804c-806e6f6e6963}#000000000000000		0x00000080	0x00000000	No	No	03/06/2019 20:56:09	03/06/2019 20:56:09		{3f7bf14c-76ad-5e03-3471-b03c3c4cc}	Driver volume con file system WPD	10.0.17763.1	wpdfs.inf	Basic_Install	21/06/2006	11/05/2019 01:06:04
Generic volume shadow copy	Microsoft		VolumeSnapshot		STORAGE\VolumeSnapshot\HarddiskVolumeSnapshot1		0x00000080	0x00000000	No	No	11/05/2019 01:03:37			{00000000-0000-0000-FFFF-ffffffffffff}	Generic volume shadow copy	10.0.17763.1	volsnap.inf	volume_snapshot_install.NTamd64	21/06/2006	11/05/2019 00:58:56
Generic volume shadow copy	Microsoft		VolumeSnapshot		STORAGE\VolumeSnapshot\HarddiskVolumeSnapshot2		0x00000080	0x00000000	No	No	11/05/2019 01:03:37			{00000000-0000-0000-FFFF-ffffffffffff}	Generic volume shadow copy	10.0.17763.1	volsnap.inf	volume_snapshot_install.NTamd64	21/06/2006	11/05/2019 00:58:56
Generic volume shadow copy	Microsoft		VolumeSnapshot		STORAGE\VolumeSnapshot\HarddiskVolumeSnapshot3		0x00000080	0x00000000	No	No	11/05/2019 01:03:37			{00000000-0000-0000-FFFF-ffffffffffff}	Generic volume shadow copy	10.0.17763.1	volsnap.inf	volume_snapshot_install.NTamd64	21/06/2006	11/05/2019 00:58:56
Generic volume shadow copy	Microsoft		VolumeSnapshot		STORAGE\VolumeSnapshot\HarddiskVolumeSnapshot4		0x00000080	0x00000000	No	No	11/05/2019 01:03:37			{00000000-0000-0000-FFFF-ffffffffffff}	Generic volume shadow copy	10.0.17763.1	volsnap.inf	volume_snapshot_install.NTamd64	21/06/2006	11/05/2019 00:58:56
Generic volume shadow copy	Microsoft		VolumeSnapshot		STORAGE\VolumeSnapshot\HarddiskVolumeSnapshot5		0x00000080	0x00000000	No	No	11/05/2019 01:03:37			{00000000-0000-0000-FFFF-ffffffffffff}	Generic volume shadow copy	10.0.17763.1	volsnap.inf	volume_snapshot_install.NTamd64	21/06/2006	11/05/2019 00:58:56
Generic volume shadow copy	Microsoft		VolumeSnapshot		STORAGE\VolumeSnapshot\HarddiskVolumeSnapshot6		0x00000080	0x00000000	No	No	11/05/2019 01:36:20			{00000000-0000-0000-FFFF-ffffffffffff}	Generic volume shadow copy	10.0.17763.1	volsnap.inf	volume_snapshot_install.NTamd64	21/06/2006	11/05/2019 01:36:20
HID Keyboard Device	(Standard keyboards)	kbdhid	Keyboard		HID\VID_04F2&PID_0116\6&2440446b&0&0000		0x00000084	0x00000000	No	No	11/05/2019 01:32:17	11/05/2019 00:59:04		{908ce005-737f-11e9-93f3-806e6f6e6963}	HID Keyboard Device	10.0.17763.348	keyboard.inf	HID_Keyboard_Inst.NT	21/06/2006	11/05/2019 00:59:04
HID-compliant mouse	Microsoft	mouhid	Mouse		HID\VID_04F2&PID_0939\6&2ea199f3&0&0000		0x00000080	0x00000000	No	No	11/05/2019 01:03:37	11/05/2019 00:59:04		{908ce006-737f-11e9-93f3-806e6f6e6963}	HID-compliant mouse	10.0.17763.1	mnmouse.inf	HID_Mouse_Inst.NT	21/06/2006	11/05/2019 00:59:04
High Definition Audio Controller	Microsoft	HDAudBus	System		PCI\VEN_1002&DEV_4383&SUBSYS_11511849&REV_40\3&267a616a&0&A2	@System32\drivers\pci.sys,#65536;PCI bus %1, device %2, function %3;(0,20,2)	0x00000080	0x00000000	No	Yes	03/06/2019 20:55:46	11/05/2019 00:58:54		{00000000-0000-0000-FFFF-ffffffffffff}	High Definition Audio Controller	10.0.17763.1	hdaudbus.inf	HDAudio_Device.NT	14/09/2018	11/05/2019 00:58:54
High Definition Audio Controller	Microsoft	HDAudBus	System		PCI\VEN_1002&DEV_AAC0&SUBSYS_AAC01748&REV_00\4&1d09f1&0&0110	@System32\drivers\pci.sys,#65536;PCI bus %1, device %2, function %3;(1,0,1)	0x00000080	0x00000000	No	Yes	03/06/2019 20:55:46	11/05/2019 00:58:54		{00000000-0000-0000-FFFF-ffffffffffff}	High Definition Audio Controller	10.0.17763.1	hdaudbus.inf	HDAudio_Device.NT	14/09/2018	11/05/2019 00:58:54
High precision event timer	(Standard system devices)		System		ACPI\PNP0103\2&daba3ff&2		0x00000020	0x00000000	No	No	11/05/2019 00:59:14	11/05/2019 00:58:54		{00000000-0000-0000-FFFF-ffffffffffff}	High precision event timer	10.0.17763.1	machine.inf	NO_DRV_HPET	21/06/2006	11/05/2019 00:58:54
HP 27k Display	HP	monitor	Monitor		DISPLAY\HWP3326\1&8713bca6&UID0		0x00000084	0x00000000	No	No	11/05/2019 11:28:48	11/05/2019 00:59:24		{e8c76255-7a3e-530f-92f5-147da35e4223}	HP 27k Display	1.0.0.0	oem15.inf	27k_H2.Install	17/11/2015	11/05/2019 11:28:48
HP 27k Display	HP	monitor	Monitor		DISPLAY\HWP3326\5&1ffbbd68&5&UID261		0x00000084	0x00000000	No	No	11/05/2019 01:07:04	11/05/2019 01:07:04		{f6c6ad53-78b9-54e2-973a-a667c9440db7}	HP 27k Display	1.0.0.0	oem15.inf	27k_H2.Install	17/11/2015	11/05/2019 01:07:04
Linea (WsAudioDevice_3835(1))	Microsoft		AudioEndpoint		SWD\MMDEVAPI\{0.0.1.00000000}.{74854c13-8e15-4c93-9bea-dd92d9544ffb}		0x00000080	0x00000000	No	No	11/05/2019 01:06:21			{00000000-0000-0000-FFFF-ffffffffffff}	Audio Endpoint	10.0.17763.1	audioendpoint.inf	NO_DRV	14/09/2018	11/05/2019 01:06:21
MediaAccess TG788vn v2	Technicolor		SoftwareDevice		SWD\DAFUPnPProvider\uuid:6cfa3fa4-f1d6-57fa-b12a-312085312191f	http://192.168.1.253:41952/dstr/b5qQa0/	0x00000080	0x00000000	No	No	11/05/2019 01:26:50			{6cfa3fa4-f1d6-57fa-b12a-312085312191f}	Generic software device	10.0.17763.1	c_swdevice.inf	SoftwareDevice	21/06/2006	11/05/2019 01:26:50
Microsoft ACPI-Compliant System	Microsoft	ACPI	System		ACPI_HAL\PNP0C08\0		0x00000030	0x00000000	No	Yes	03/06/2019 20:55:31	11/05/2019 00:58:54		{00000000-0000-0000-FFFF-ffffffffffff}	Microsoft ACPI-Compliant System	10.0.17763.1	acpi.inf	ACPI_Inst.NT	21/06/2006	11/05/2019 00:58:53
Microsoft Basic Display Driver	(Standard display types)	BasicDisplay	System		ROOT\BasicDisplay\0000		0x00000000	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 00:58:59		{00000000-0000-0000-FFFF-ffffffffffff}	Microsoft Basic Display Driver	10.0.17763.1	basicdisplay.inf	MSBDD_Fallback	21/06/2006	11/05/2019 00:59:24
Microsoft Basic Render Driver	Microsoft	BasicRender	System		ROOT\BasicRender\0000		0x00000000	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 00:58:59		{00000000-0000-0000-FFFF-ffffffffffff}	Microsoft Basic Render Driver	10.0.17763.1	basicrender.inf	BasicRender	21/06/2006	11/05/2019 00:58:59
Microsoft Device Association Root Enumerator	Microsoft		SoftwareDevice		SWD\MSDAS\{ce958e9a-424f-4c88-86f4-1131482fe75a}		0x00000080	0x00000000	No	No	11/05/2019 01:26:18			{00000000-0000-0000-FFFF-ffffffffffff}	Generic software device	10.0.17763.1	c_swdevice.inf	SoftwareDevice	21/06/2006	11/05/2019 01:26:18
Microsoft Hyper-V Virtualization Infrastructure Driver	Microsoft	Vid	System		ROOT\VID\0000		0x00000080	0x00000000	No	Yes	11/05/2019 00:59:14	11/05/2019 00:58:59		{00000000-0000-0000-FFFF-ffffffffffff}	Microsoft Hyper-V Virtualization Infrastructure Driver	10.0.17763.194	wvid.inf	Vid_Device_Client.NT	21/06/2006	11/05/2019 00:58:53
Microsoft Kernel Debug Network Adapter	Microsoft	kdnic	Net		ROOT\KDNIC\0000		0x00000000	0x00000000	No	Yes	11/05/2019 00:59:43	02/06/2019 16:31:27		{00000000-0000-0000-FFFF-ffffffffffff}	Microsoft Kernel Debug Network Adapter	10.0.17763.1	kdnic.inf	KDNIC.nd	21/06/2006	11/05/2019 00:59:43
Microsoft Print to PDF	Microsoft		PrintQueue		SWD\PRINTENUM\{B485FDC0-B173-4E3C-9583-E61BDB0F4DDB}		0x00000084	0x00000000	No	No	11/05/2019 01:21:56			{d397368a-724c-4e4f-d64c-c8234ba29a8b}	Local Print Queue	10.0.17763.1	printqueue.inf	NO_DRV_LOCAL	21/06/2006	11/05/2019 01:21:56
Microsoft Radio Device Enumeration Bus	Microsoft		SoftwareDevice		SWD\RADIO\{3DB5895D-CC28-44B3-AD3D-8F01A7828D02}		0x00000080	0x00000000	No	No	11/05/2019 01:26:14			{00000000-0000-0000-FFFF-ffffffffffff}	Generic software device	10.0.17763.1	c_swdevice.inf	SoftwareDevice	21/06/2006	11/05/2019 01:26:14
Microsoft RRAS Root Enumerator	Microsoft		SoftwareDevice		SWD\MSRRAS\{5e259276-bc7e-40e3-b93b-8f89b5f3abc0}		0x00000080	0x00000000	No	No	11/05/2019 02:17:25			{00000000-0000-0000-FFFF-ffffffffffff}	Generic software device	10.0.17763.1	c_swdevice.inf	SoftwareDevice	21/06/2006	11/05/2019 02:17:25
Microsoft Storage Spaces Controller	Microsoft	spaceport	SCSIAdapter		ROOT\spaceport\0000		0x00000030	0x00000000	No	Yes	11/05/2019 01:03:37			{00000000-0000-0000-FFFF-ffffffffffff}	Microsoft Storage Spaces Controller	10.0.17763.529	spaceport.inf	Spaceport_Install	21/06/2006	30/05/2019 22:26:25
Microsoft Streaming Clock Proxy	Microsoft	MSPCLOCK	MEDIA		SW\{97bbacc-95bd-11d0-a3ea-00a0c9223196}\{53172480-4791-11D0-A5D6-28DB04C10000}		0x00000080	0x00000000	No	No	11/05/2019 01:06:16			{00000000-0000-0000-FFFF-ffffffffffff}	Microsoft Streaming Clock Proxy	10.0.17763.1	ksfilter.inf	MSPCLOCK.NT	21/06/2006	11/05/2019 01:06:16
Microsoft Streaming Quality Manager Proxy	Microsoft	MSPQM	MEDIA		SW\{ddf4358a-bb2c-11d0-a42f-00a0c9223196}\{97EBAAC8-95BD-11D0-43EA-00A0C9223196}		0x00000080	0x00000000	No	No	11/05/2019 01:06:16			{00000000-0000-0000-FFFF-ffffffffffff}	Microsoft Streaming Quality Manager Proxy	10.0.17763.1	ksfilter.inf	MSPQM.NT	21/06/2006	11/05/2019 01:06:16
Microsoft Streaming Service Proxy	Microsoft	MSKSSRV	MEDIA		SW\{96E080C7-143C-11D1-B40F-00A0C9223196}\{3CD5501A-140B-11D1-840F-00A0C9223196}		0x00000080	0x00000000	No	No	11/05/2019 01:06:16			{00000000-0000-0000-FFFF-ffffffffffff}	Microsoft Streaming Service Proxy	10.0.17763.1	ksfilter.inf	MSKSSRV.NT	21/06/2006	11/05/2019 01:06:16
Microsoft Streaming Tee/Sink-to-Sink Converter	Microsoft	MSTEE	MEDIA		SW\{c6f86f91-9bc2-11d0-8298-00009229a8a}\{DA4E2A0-7E70-11D0-A5D6-28DB04C10000}		0x00000080	0x00000000	No	No	11/05/2019 01:06:16			{00000000-0000-0000-FFFF-ffffffffffff}	Microso

Standard OpenHCD USB Host Controller	(Standard USB Host Controller)	usbohci	USB		PCI\VEN_1002&DEV_4397&SUBSYS_43971849&REV_00\3&267a616a&0&B0	@System32\drivers\pci.sys,#65536;PCI bus %1, device %2, function %3;(0,22,0)	0x00000000	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 00:59:01	{00000000-0000-0000-ffff-ffffffffffff}	Standard OpenHCD USB Host Controller	10.0.17763.1	usbport.inf	OHCI.Dev.NT	21/06/2006	11/05/2019 00:58:54
Standard OpenHCD USB Host Controller	(Standard USB Host Controller)	usbohci	USB		PCI\VEN_1002&DEV_4399&SUBSYS_43991849&REV_00\3&267a616a&0&A5	@System32\drivers\pci.sys,#65536;PCI bus %1, device %2, function %3;(0,20,5)	0x00000000	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 00:59:01	{00000000-0000-0000-ffff-ffffffffffff}	Standard OpenHCD USB Host Controller	10.0.17763.1	usbport.inf	OHCI.Dev.NT	21/06/2006	11/05/2019 00:58:54
System board	(Standard system devices)		System		ACPI\PNP0C01\1		0x00000030	0x00000000	No	No	11/05/2019 00:59:14	11/05/2019 00:58:54	{00000000-0000-0000-ffff-ffffffffffff}	System board	10.0.17763.1	machine.inf	NO_DRV_MBRES	21/06/2006	11/05/2019 00:58:54
System board	(Standard system devices)		System		ACPI\PNP0C01\c8		0x00000030	0x00000000	No	No	11/05/2019 00:59:14	11/05/2019 00:58:54	{00000000-0000-0000-ffff-ffffffffffff}	System board	10.0.17763.1	machine.inf	NO_DRV_MBRES	21/06/2006	11/05/2019 00:58:54
System CMOS/real time clock	(Standard system devices)		System		ACPI\PNP0B00\4&8ab8035&0		0x00000060	0x00000000	No	No	03/06/2019 20:55:31	11/05/2019 00:58:54	{00000000-0000-0000-ffff-ffffffffffff}	System CMOS/real time clock	10.0.17763.1	machine.inf	NO_DRV_X	21/06/2006	11/05/2019 00:58:54
System speaker	(Standard system devices)		System		ACPI\PNP0800\4&8ab8035&0		0x00000020	0x00000000	No	No	11/05/2019 00:59:14	11/05/2019 00:58:54	{00000000-0000-0000-ffff-ffffffffffff}	System speaker	10.0.17763.1	machine.inf	NO_DRV_X	21/06/2006	11/05/2019 00:58:54
System timer	(Standard system devices)		System		ACPI\PNP0100\4&8ab8035&0		0x00000020	0x00000000	No	No	11/05/2019 00:59:14	11/05/2019 00:58:54	{00000000-0000-0000-ffff-ffffffffffff}	System timer	10.0.17763.1	machine.inf	NO_DRV_X	21/06/2006	11/05/2019 00:58:54
TP-LINK Wireless USB Adapter	TP-LINK	arthur	Net		USB\VID_0CF3&PID_7015\112345	Port_#0004.Hub_#0002	0x00000014	0x00000000	No	Yes	11/05/2019 01:07:01	11/05/2019 01:07:03	{7cac4b2d-a986-52d0-8058-8aa2d661a5a0}	TP-LINK Wireless USB Adapter	2.0.0.62	oem18.inf	ATHER_DEV_7015.ndi.NTamd64	20/04/2011	03/06/2019 19:11:43
UMBus Root Bus Enumerator	Microsoft	umbus	System		ROOT\UMBUS\0000		0x00000000	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 00:58:53	{00000000-0000-0000-FFFF-FFFFFFFFFFFF}	UMBus Root Bus Enumerator	10.0.17763.1	umbus.inf	UmBusRoot_Device.NT	21/06/2006	11/05/2019 00:58:53
USB Input Device	(Standard system devices)	HidUsb	HIDClass		USB\VID_04F2&PID_0116\5&a2234ed&0&1	Port_#0001.Hub_#0001	0x00000084	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 00:59:10	{909ce005-737f-11e9-93f3-806e6f6e6963}	USB Input Device	10.0.17763.379	input.inf	HID_Inst.NT	21/06/2006	11/05/2019 00:59:03
USB Input Device	(Standard system devices)	HidUsb	HIDClass		USB\VID_04F2&PID_0939\5&a2234ed&0&3	Port_#0003.Hub_#0001	0x00000084	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 00:59:10	{909ce006-737f-11e9-93f3-806e6f6e6963}	USB Input Device	10.0.17763.379	input.inf	HID_Inst.NT	21/06/2006	11/05/2019 00:59:04
USB Mass Storage Device	Compatible USB storage device	USBSTOR	USB		USB\VID_1058&PID_1042\57584131453432564C413636	Port_#0008.Hub_#0008	0x00000094	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 00:58:55	{37ef14c-76ad-5940-9019-34713c03c4cc}	USB Mass Storage Device	10.0.17763.1	usbstor.inf	USBSTOR_BULK.NT	21/06/2006	11/05/2019 00:58:55
USB Mass Storage Device	Compatible USB storage device	USBSTOR	USB		USB\VID_1058&PID_25A2\575841314137384E50524435	Port_#0007.Hub_#0008	0x00000094	0x00000000	No	No	25/05/2019 12:34:14	25/05/2019 12:34:14	{5834a676-9e57-5aed-a6ae-47f7424cdabe}	USB Mass Storage Device	10.0.17763.1	usbstor.inf	USBSTOR_BULK.NT	21/06/2006	25/05/2019 12:34:14
USB Root Hub	(Standard USB Host Controller)	usbhub	USB		USB\ROOT_HUB\4&11c87fd2\0&0		0x00000080	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 01:16:47	{00000000-0000-0000-ffff-ffffffffffff}	USB Root Hub	10.0.17763.1	usbport.inf	ROOTHUB.Dev.NT	21/06/2006	11/05/2019 00:59:01
USB Root Hub	(Standard USB Host Controller)	usbhub	USB		USB\ROOT_HUB\4&20ff5f8&0		0x00000080	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 01:16:47	{00000000-0000-0000-ffff-ffffffffffff}	USB Root Hub	10.0.17763.1	usbport.inf	ROOTHUB.Dev.NT	21/06/2006	11/05/2019 00:59:01
USB Root Hub	(Standard USB Host Controller)	usbhub	USB		USB\ROOT_HUB\4&229c60d3d&0		0x00000080	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 01:16:47	{00000000-0000-0000-ffff-ffffffffffff}	USB Root Hub	10.0.17763.1	usbport.inf	ROOTHUB.Dev.NT	21/06/2006	11/05/2019 00:59:01
USB Root Hub	(Standard USB Host Controller)	usbhub	USB		USB\ROOT_HUB\4&367ff78&0		0x00000080	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 01:16:47	{00000000-0000-0000-ffff-ffffffffffff}	USB Root Hub	10.0.17763.1	usbport.inf	ROOTHUB.Dev.NT	21/06/2006	11/05/2019 00:59:01
USB Root Hub	(Standard USB Host Controller)	usbhub	USB		USB\ROOT_HUB20\4&148cab26&0		0x00000080	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 01:16:47	{00000000-0000-0000-ffff-ffffffffffff}	USB Root Hub	10.0.17763.1	usbport.inf	ROOTHUB.Dev.NT	21/06/2006	11/05/2019 00:58:55
USB Root Hub	(Standard USB Host Controller)	usbhub	USB		USB\ROOT_HUB20\4&2d6e04d1&0		0x00000080	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 01:16:47	{00000000-0000-0000-ffff-ffffffffffff}	USB Root Hub	10.0.17763.1	usbport.inf	ROOTHUB.Dev.NT	21/06/2006	11/05/2019 00:58:55
USB Root Hub	(Standard USB Host Controller)	usbhub	USB		USB\ROOT_HUB20\4&2e1cc1d0&0		0x00000080	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 01:16:47	{00000000-0000-0000-ffff-ffffffffffff}	USB Root Hub	10.0.17763.1	usbport.inf	ROOTHUB.Dev.NT	21/06/2006	11/05/2019 00:58:55
USB Root Hub (USB 3.0)	(Standard USB HUBs)	USBHUB3	USB		USB\ROOT_HUB30\5&110cc0a0&0&0		0x00000080	0x00000000	No	No	11/05/2019 01:03:37	11/05/2019 00:58:55	{00000000-0000-0000-ffff-ffffffffffff}	USB Root Hub (USB 3.0)	10.0.17763.1	usbhub3.inf	Generic.Install.NT	14/09/2018	11/05/2019 00:58:55
USB Root Hub (USB 3.0)	(Standard USB HUBs)	USBHUB3	USB		USB\ROOT_HUB30\5&2a1c4813&0&0		0x00000080	0x00000000	No	Yes	11/05/2019 01:03:37	28/05/2019 18:22:59	{00000000-0000-0000-ffff-ffffffffffff}	USB Root Hub (USB 3.0)	10.0.17763.1	usbhub3.inf	Generic.Install.NT	14/09/2018	11/05/2019 00:58:55
Virtual CloneDrive	Elaborate Bytes AG	VClone	SCSIAdapter		ROOT\SCSIADAPTER\0000		0x00000000	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 00:58:53	{00000000-0000-0000-FFFF-FFFFFFFFFFFF}	Virtual CloneDrive	5.4.7.0	oem5.inf	miniport	24/07/2013	11/05/2019 00:58:53
Volume	Microsoft	volume	Volume		STORAGE\Volume\{45a6d187-f3ec-11e8-a06c-806e6f6e6963}#0000000000100000		0x00000080	0x00000000	No	No	25/05/2019 12:34:20	25/05/2019 12:34:20	{5834a676-9e57-5aed-a6ae-47f7424cdabe}	Volume	10.0.17763.1	volume.inf	volume_install.NT	21/06/2006	25/05/2019 12:34:20
Volume	Microsoft	volume	Volume		STORAGE\Volume\{849afeed-4852-11e6-804e-806e6f6e6963}#0000000000000000		0x00000080	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 00:58:55	{37ef14c-76ad-5940-9019-34713c03c4cc}	Volume	10.0.17763.1	volume.inf	volume_install.NT	21/06/2006	11/05/2019 00:58:55
Volume	Microsoft	volume	Volume		STORAGE\Volume\{c9f64820-6ed6-11e6-b1f2-806e6f6e6963}#0000000000007E00		0x00000080	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 00:58:55	{00000000-0000-0000-ffff-ffffffffffff}	Volume	10.0.17763.1	volume.inf	volume_install.NT	21/06/2006	11/05/2019 00:58:55
Volume	Microsoft	volume	Volume		STORAGE\Volume\{c9f64820-6ed6-11e6-b1f2-806e6f6e6963}#0000000002800000		0x00000080	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 00:58:55	{00000000-0000-0000-ffff-ffffffffffff}	Volume	10.0.17763.1	volume.inf	volume_install.NT	21/06/2006	11/05/2019 00:58:55
Volume Manager	Microsoft	volmgr	System		ROOT\volmgr\0000		0x00000030	0x00000000	No	Yes	11/05/2019 01:03:37		{00000000-0000-0000-FFFF-FFFFFFFFFFFF}	Volume Manager	10.0.17763.168	volmgr.inf	Volmgr	21/06/2006	11/05/2019 00:58:54
WAN Miniport (IKEv2)	Microsoft	RasAgileVpn	Net		SW\{1MSRRAS\MS_AGILEVPNMINIPORT		0x00000010	0x00000000	No	Yes	11/05/2019 02:17:27	02/06/2019 16:31:27	{00000000-0000-0000-ffff-ffffffffffff}	WAN Miniport (IKEv2)	10.0.17763.1	netavpna.inf	Ndi-Mp-AgileVpn	21/06/2006	11/05/2019 02:17:29
WAN Miniport (IP)	Microsoft	NdisWan	Net		SW\{1MSRRAS\MS_NDISWANIP		0x00000010	0x00000000	No	Yes	11/05/2019 02:17:28	02/06/2019 16:31:27	{00000000-0000-0000-ffff-ffffffffffff}	WAN Miniport (IP)	10.0.17763.1	netrasa.inf	Ndi-Mp-Ip	21/06/2006	11/05/2019 02:17:28
WAN Miniport (IPv6)	Microsoft	NdisWan	Net		SW\{1MSRRAS\MS_NDISWANIPV6		0x00000010	0x00000000	No	Yes	11/05/2019 02:17:28	02/06/2019 16:31:27	{00000000-0000-0000-ffff-ffffffffffff}	WAN Miniport (IPv6)	10.0.17763.1	netrasa.inf	Ndi-Mp-Ipv6	21/06/2006	11/05/2019 02:17:28
WAN Miniport (L2TP)	Microsoft	Rasl2tp	Net		SW\{1MSRRAS\MS_L2TPMINIPORT		0x00000010	0x00000000	No	Yes	11/05/2019 02:17:27	02/06/2019 16:31:27	{00000000-0000-0000-ffff-ffffffffffff}	WAN Miniport (L2TP)	10.0.17763.1	netrasa.inf	Ndi-Mp-L2tp	21/06/2006	11/05/2019 02:17:29
WAN Miniport (Network Monitor)	Microsoft	NdisWan	Net		SW\{1MSRRAS\MS_NDISWANBH		0x00000010	0x00000000	No	Yes	11/05/2019 02:17:29	02/06/2019 16:31:27	{00000000-0000-0000-ffff-ffffffffffff}	WAN Miniport (Network Monitor)	10.0.17763.1	netrasa.inf	Ndi-Mp-Bh	21/06/2006	11/05/2019 02:17:29
WAN Miniport (PPPOE)	Microsoft	RasPppoe	Net		SW\{1MSRRAS\MS_PPPOEMINIPORT		0x00000010	0x00000000	No	Yes	11/05/2019 02:17:28	02/06/2019 16:31:27	{00000000-0000-0000-ffff-ffffffffffff}	WAN Miniport (PPPOE)	10.0.17763.1	netrasa.inf	Ndi-Mp-Pppoe	21/06/2006	11/05/2019 02:17:29
WAN Miniport (PPTP)	Microsoft	PptpMiniport	Net		SW\{1MSRRAS\MS_PPTPMINIPORT		0x00000010	0x00000000	No	Yes	11/05/2019 02:17:27	02/06/2019 16:31:27	{00000000-0000-0000-ffff-ffffffffffff}	WAN Miniport (PPTP)	10.0.17763.1	netrasa.inf	Ndi-Mp-Pptp	21/06/2006	11/05/2019 02:17:29
WAN Miniport (SSTP)	Microsoft	RasSstp	Net		SW\{1MSRRAS\MS_SSTPMINIPORT		0x00000010	0x00000000	No	Yes	11/05/2019 02:17:26	02/06/2019 16:31:27	{00000000-0000-0000-ffff-ffffffffffff}	WAN Miniport (SSTP)	10.0.17763.1	netsstpa.inf	Ndi-Mp-Sstp	21/06/2006	11/05/2019 02:17:29
WD Elements 1042 USB Device	(Standard disk drives)	disk	DiskDrive		USBSTOR\Disk&Ven_WD&Prod_Elements_1042&Rev_1019\57584131453432564C413636\0&0		0x00000010	0x00000000	No	Yes	11/05/2019 01:03:37	11/05/2019 00:58:55	G:\	{37ef14c-76ad-5940-9019-34713c03c4cc}	Disk drive	10.0.17763.1	disk.inf	disk_install.NT	21/06/2006	11/05/2019 00:58:55
WD Elements 25A2 USB Device	(Standard disk drives)	disk	DiskDrive		USBSTOR\Disk&Ven_WD&Prod_Elements_25A2&Rev_1021\575841314137384E50524435\0&0		0x00000010	0x00000000	No	No	25/05/2019 12:34:19	25/05/2019 12:34:19	{5834a676-9e57-5aed-a6ae-47f7424cdabe}	Disk drive	10.0.17763.1	disk.inf	disk_install.NT	21/06/2006	25/05/2019 12:34:19
WuAudioDevice_3835(1)	WuAudioDevice_3835(1)	WuAudioDevice_3835(1)	MEDIA		ROOT\MEDIA\0000		0x00000000	0x00000000	No	Yes	11/05/2019 01:06:15	11/05/2019 01:06:15	{00000000-0000-0000-FFFF-FFFFFFFFFFFF}	WuAudioDevice_3835(1)	5.0.1.0	oem14.inf	VirtualAudio.NT	21/07/2008	11/05/2019 01:06:16